

Report of results of car state inspection

32 - 22.05.2015 17:11:39

Client name **xxxx**
Phone number
Mark
Model **PATRIOT**
Year **2013**
Car number **xxx**
VIN **XTT236300D00XXXXX**
Mileage **19200 km**
Master name **www.VM256.ru**

Bosch ME 17.9.7

ScanDoc data (parameters/identification)

Name	Value
Calibration programm date	00_____
VIN	20-06-2013
	VM35B292__
	06 58 12 82 10 94 20 06
	ME17.9.7__
	3163-3763014-20
	0261S07321
	1037521336
	ZMZ-40905.10__

ScanDoc data (parameters/identification)

Name		Value
		798 /
		79,50° C
		13,7
		3,61%
	1	3,62
2 2,	1	0,000
	(MAP)	42
	(MAP)	1,7
	N1	0,43
	N2	2,87
		0,00%
	N1	0,45
	N2	0,22
		0 /
		30,00° C
		.
		810 /
		100,0%
	/	1,000
		0
	. 1	0,2316
	. 2	0,1826
	. 3	0,1733
	. 4	0,1727
		20,16%
		1,569 /
1		.
2		.
		.
		.
	/	1,009

	48,75° C
. 1	7,50°
. 2	7,50°
. 3	6,00°
. 4	6,75°
	3,9 /

ScanDoc data (parameters/identification)

2500

Name		Value
		2531 /
		77,25° C
		13,5
		8,22%
	1	2,73
2 2,	1	0,000
	(MAP)	30
	(MAP)	1,2
	N1	0,55
	N2	2,76
		23,77%
	N1	1,04
	N2	0,52
		0 /
		30,00° C
		.
		1520 /
		100,0%
	/	1,000
		0
	. 1	0,7223
	. 2	0,6412
	. 3	0,6076
	. 4	0,6843
		15,28%
		3,575 /
1		.
2		.
		.
		.
	/	0,933

	48,75° C
. 1	42,00°
. 2	42,00°
. 3	42,00°
. 4	42,00°
	3,9 /

Signature _____

Stamp